

APPENDIX II
SITE PHOTOGRAPHS

*Area 2-J & D Towing;
Sites 5 & 6*



PHOTO 1

Mobile trailer used as an office on Site 5.



PHOTO 2

Three-sided garage where automotive work is performed on Site 5.



PHOTO 3

Area where automotive work is performed adjacent to the three-sided garage.



PHOTO 4

Pooled automotive waste fluids on exposed soils in area where automotive work is performed.



PHOTO 5

Drums containing improperly stored automotive waste fluids on Site 5.



PHOTO 6

Drums containing improperly stored automotive waste fluids on Site 5.



PHOTO 7

AST and associated staining to exposed soils on Site 5.



PHOTO 8

East side of junkyard looking west on Site 5.



PHOTO 9

Building debris near east property boundary on Site 5.



PHOTO 10

Typical junk storage, staining and impacted ponded water observed on exposed soils in junkyard on Site 5.



PHOTO 11

Typical automotive junk storage practices, staining observed on exposed soils and impacted ponded water in junkyard on Site 5.



PHOTO 12

Midlothian Creek along the north side of Site 5.



PHOTO 13

West side of Site 6 looking east.



PHOTO 14

Junk yard on Site 6.



PHOTO 15

Ponded water on Site 6.



PHOTO 16

Abandoned residence on Site 6.



PHOTO 17

Abandoned shed on Site 6.



PHOTO 18

Debris on east side of Site 6.